

Inspection Photos

Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad

Location #: 334900



Photo # 9965 From entrance to location



Photo # 9971 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad

Location #: 334900



Jun 9, 2023 at 10:36:30 AM
CO



Jun 9, 2023 at 10:36:47 AM
CO

Photo # 9972 Location

Photo # 9973 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad
Location #: 334900



Photo # 9968 Location



Photo # 9970 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad
Location #: 334900



Photo # 9976 Debris



Photo # 9977 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad

Location #: 334900



Photo # 9988 Debris



Photo # 9978 Flowline heating insulation open ended



Inspection Photos

Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad

Location #: 334900



Photo # 9980 Containment liner needs maintenance



Photo # 9981 Containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad

Location #: 334900



Photo # 9985 Flowline heating insulation open ended



Photo # 9986 Flowline heating insulation open ended



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: CAERUS PICEANCE LLC PITMAN E13W Pad
Location #: 334900



Photo # 9987 Flowline heating insulation open ended



Photo # 9989 Flowline heating insulation open ended

