


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



Location Overview:
Section/Township/Range: 16 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



**Photo # 5694 From Inspection 708900299
conducted on 04/18/2023 Erosion & transport of
sediment off location**



**Photo # 9685 Erosion & transport of sediment off
location**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



Photo # 5695 From Inspection 708900299 conducted on 04/18/2023 Erosion & transport of sediment off location



Photo # 9692 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



Photo # 9684 Erosion & transport of sediment off location



Photo # 9686 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



Photo # 9687 Erosion & transport of sediment off location



Photo # 9688 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 104 Pad
Location ID: 322416



Photo # 9693 Erosion & transport of sediment off location