



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Unable to access location due to lock on gate

Corrective Action: Provide access to locaton per COGCC rules

Date: 06/05/2023

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 204395 Type: WELL API Number: 005-06480 Status: TA Insp. Status: TA

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 04/16/2018

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Annual UIC inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: GRAVITY FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is in need of MIT, previous MIT was performed on 4/16/18, i need of 5 year MIT.

Corrective Action: Comply with COGCC mechanical integrity testing rules Date: 06/05/2023

**COGCC Comments**

Comment	User	Date
<p><u>COGCC Inspection Report Summary</u>                      On 6/5/23 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Reeves 32-21 4                      Company Name- Axis                      API- 05-005-06480                      In Arapahoe County Colorado.                      While there, I observed IJ well                      During this inspection the following possible compliance issues were observed:                      Unable to access Location due to lock on gate                      Proved access to location per COGCC rules 6/5/23                      Well is in need of MIT, previous MIT was performed on 4/16/18, i need of 5 year MIT.                      Comply with COGCC mechanical integrity testing rules 6/5/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	06/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403424696	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6137291</a>
699504770	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136935">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6136935</a>