

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2023

Submitted Date:

06/08/2023

Document Number:

694500578

FIELD INSPECTION FORMLoc ID 467526 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Ross, Rikki	417-773-2341	Rikki.Ross@fulcrumeo.com	
Penner, Annalee		Annalee.Penner@fulcrumeo.com	
Blohm, Justin	520-820-2380	justin.blohm@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467526	LOCATION	AC			-	Spicer S32 Annex Pad	EI
481711	WELL	DG	06/15/2022	LO	057-06626	SU Spicer 0680 4-5H17	EI
481712	WELL	DG	06/16/2022	LO	057-06627	SU Spicer 0680 3-5H17	EI
481713	WELL	DG	06/17/2022	LO	057-06628	SU Spicer 0680 2-5H17	EI
481714	WELL	DG	06/19/2022	LO	057-06629	SU Spicer 0680 1-5H17	EI

General Comment:

COGCC staff, Kris Neidel, inspected the Spicer Annex pad and spill # 484557. The following was observed; weather was 70 degrees and mostly cloudy, a work over rig was on location, flowing back well to open-top tank, This tank was the source of this spill. Free fluid was removed from pad surface. NO soil has been removed. At the time of inspection, the well was flowing back to open top tank, staff did not approach the rig crew with the well flowing to the tank.

Corrective Action: Remove stained soil from spill 484557. There were other staining on the pad from drill rig and completions. see attached photos. The other areas should be removed from pad and confirmation samples collected to verify compliance with Table 915-1.

Inspected Facilities				
Facility ID: <u>467526</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>481711</u>	Type: <u>WELL</u>	API Number: <u>057-06626</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>481712</u>	Type: <u>WELL</u>	API Number: <u>057-06627</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>481713</u>	Type: <u>WELL</u>	API Number: <u>057-06628</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>
Facility ID: <u>481714</u>	Type: <u>WELL</u>	API Number: <u>057-06629</u>	Status: <u>DG</u>	Insp. Status: <u>EI</u>

Environmental**Spill/Remediation:**

Comment: Spill was reported, spill #484557. Other areas of staining on pad.

Corrective Action: Remove stained soil from spill 484557. There were other staining on the pad from drill rig and completions on pad southeast side where the pad "road" was during drilling and near southwest side of pad, see attached photos. The other areas should be removed from pad and confirmation samples collected to verify compliance with Table 915-1.

Date: 09/06/2023

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403428257	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6140713
694500579	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6140710