

Inspection Photos

API: 067-05521

Operator: LOGOS OPERATING LLC

Inspection Date: 6/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 1. Facing northwest along the access road. There is vehicle rutting and tracking along the road that needs to be repaired and stabilized. There are also noxious weeds along the roadside that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 2. Facing northwest along the access road. There is vehicle rutting and tracking along the road that needs to be repaired and stabilized. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 3. Facing northwest along the access road. This area had previously washed out and was repaired however, stormwater is directed down this area and there are no BMP's to divert off the road e.g. culvert water bar ect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 4. Facing northeast toward the wellsite.



Inspection Photos



Photo 5. The netting on the buried tank is not maintained to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023

Inspection Photos



Photo 6. Facing back to the southwest.



Inspection Photos



Photo 7. There is an electric utility that has fallen over at the northside of the location and needs to be removed or repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333537 | Date: 6/15/2023