

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-07 (F1) PAD

Location ID: 334778



Photo #380 From entrance to location.



Photo #381 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-07 (F1) PAD

Location ID: 334778



Photo #386 Unused equipment.



Photo #389 Calibration cards not conspicuously posted.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-07 (F1) PAD

Location ID: 334778



Photo #382 Run on to location not being controlled.



Photo #384 Run on to location not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-07 (F1) PAD

Location ID: 334778



Photo #383 Cut slope lacks stabilization.



Photo #387 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FURR /22-07 (F1) PAD

Location ID: 334778



Photo #390 Location lacks stabilization.



Photo #395 Insufficient tracking BMP at entrance to location to minimize the transport of sediment.