

Inspection Photos

Loc: 484496

Operator: NUEVIDA RESOURCES LLC

Inspection Date: 6/15/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 1. Facing southwest toward the tank pad location which is being constructed. It was slightly windy and dust from equipment was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 2. Standing at the southwest corner of the tank pad location facing northeast. Topsoil was in process of being stripped and stockpiled at the south and east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 3. Standing at the southeast corner of the tank pad location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 4. Southeast side of the location facing north. There are no perimeter stormwater controls installed. Topsoil is being paced near the drainage swale shown at red arrow which runs along the edge of the disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 5. Northeast side of the location facing south. There are no perimeter stormwater controls installed. Stormwater controls should have been installed prior to construction. Topsoil is being stripped and stockpiled along the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 6. Standing on the topsoil pile facing north. There are no perimeter stormwater controls installed. Stormwater controls should have been installed prior to construction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 7. Northeast side of the location facing west. There are no perimeter stormwater controls installed. Stormwater controls should have been installed prior to construction. This is the downhill gradient slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 8. Northeast corner of the location facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 9. View of test hole for topsoil evaluation.



Photo 10. Northeast corner of the location facing southwest. It appears topsoil was being salvaged around 6-8" in some areas and less in other areas but salvaging was still ongoing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 11. Facing north along the flowline disturbance. BMPs need to be installed along the flowline disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023