

# Inspection Photos

6/21/2023

Operator: PRE RESOURCES INC - 10241

Location Number: 322302

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 1:** Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos show final reclamation of the Location, including compaction alleviation, recontouring/regrading and reclaiming, has not been performed. NOTE: Vegetation observed within photo is predominantly Undesirable and Noxious Plant species such as Redstem filaree, Field Bindweed, Hoary Cress, Curly cup Gumweed, etc...



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 2:** See comments under photo 1.



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 3:** Unused pipe equipment remaining on the Location.



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 4:** Photos show cut slope remaining, as well as gravel and secondary containment berms associated with the former tank battery facility. Location has not been recontoured/regraded/reclaimed. Vegetation observed within photo is predominantly Undesirable and Noxious Plant species such as Redstem filaree, Field Bindweed, Hoary Cress, Curly cup Gumweed, etc...



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 5:** Photo shows a soil stockpile remaining on the southeast end of the Location. Vegetation observed within photo is predominantly Undesirable and Noxious Plant species such as Redstem filaree, Field Bindweed, Hoary Cress, Curly cup Gumweed, etc...



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 6:** Photos taken from the cut slopes on the east end of the Location. Photo shows Location has not been recontoured/regraded and reclaimed. Photos also example showing slopes lack stabilization; stormwater and erosion control BMPs remain missing or insufficient to stabilize slopes, and to manage runoff; erosion degradation has persisted.



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 7:** Photos taken from the access road. Photo shows road has not been reclaimed. Photo also shows stormwater and erosion control BMPs remain missing or insufficient at road; erosion degradation has persisted.



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 8:** Photos 8-9 examples showing vegetation on the Location and access road. Vegetation observed on the Location is predominantly Undesirable and Noxious Plant species such as Redstem filaree, Field Bindweed, Hoary Cress, Curly cup Gumweed, etc... Unable to find evidence that ongoing weed management activities are being performed.



## Inspection Photos

Operator Name: PRE RESOURCES INC - 10241

Location Number: 322302



**Photo 9:** See comment under photo 8. Photo taken from the access road. Vegetation in photo Hoary Cress



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources