

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1490 From entrance to location



Photo # 1491 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1493 Location



Photo # 1494 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1495 Location



Photo # 1496 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Jun 23, 2023 at 9:09:41 AM
CO



Jun 23, 2023 at 9:10:31 AM
CO

Photo # 1497 Location

Photo # 1498 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1499 Debris



Photo # 1501 Hole in production tank/tank corrosion

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Jun 23, 2023 at 9:16:55 AM
CO



Jun 23, 2023 at 9:17:03 AM
CO

Photo # 1503 Hole in production tank/tank corrosion

Photo # 1504 Hole in production tank/tank corrosion

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1505 Hole in production tank/tank corrosion



Photo # 1500 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1507 Stained gravel in secondary containment



Photo # 1509 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1521 Stained soils & gravel (Couey 31-7 wellhead)




Photo # 1524 Stained soils & gravel (Couey 31-1C2 wellhead)

Inspection Photos
Location Name: CAERUS PICEANCE LLC B31 Pad
Location ID: 335307



Photo # 1531 Stained soils & gravel (Couey 30-15 wellhead)



Photo # 1515 Flowline heating insulation open ended