

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

06/28/2023

Document Number:

708900885

FIELD INSPECTION FORMLoc ID 324047 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211569	WELL	PR	12/13/1998	GW	045-07329	CLOUGH RMV 93-21	PR

General Comment:**COGCC Inspection Report Summary**

On 06/28/2023 at approximately 10:56 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 93-21 pad.

Location # 324047 in Garfield County Colorado.

Please refer to Inspection 708900502 conducted on 05/16/2023, previous corrective action has been completed.

Location is within High Priority/Density Habitat areas.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:

	Type Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

	Type BATTERY		
Comment:	Battery sign weathered & cracking but still legible		
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
	Type OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume			
------	------	--------	--	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

	Type WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
	Type SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Taylor plug & pressure transducer located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211569	Type:	WELL	API Number:	045-07329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				Sparse
Berms						
Gravel						Sparse
Compaction						Areas of light compaction

Comment: Location appears to have some gravel throughout the location with areas of light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900886	Inspection 708900885 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6164495
708900887	Inspection 708900885 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6164496