

Interim Reclamation and Stormwater Inspection

Date: 06/28/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317118

Inspection Document #: 708200365

Washington County, CO

SWNW Section 1 T3S R54W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 1. Guy line anchors not properly marked.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 3. See comments in Photo 1.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 4. See comments in Photo 1. Additionally, rill erosion was observed on the northwest guy line anchor; soil do not appear to be properly stabilized.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 5. Undesirable vegetation (kochia and russian thistle pictured) will need to be actively managed for during this growing season.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 6. Unstabilized production areas will require maintenance and/or additional BMPs (roadbase, etc).

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 7. Stained soil around wellhead.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 8. Day tank labels are not legible and missing wildlife protection equipment.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 9. Well location requires additional signage to designate wellhead (e.g. API).

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 10. Stained soil around loadout line.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 11. Soils around partially buried tank do not appear to be stabilized with evidence of off-location sediment transport. Additional maintenance or BMPs are required to come into compliance with Rule 1002.f.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 12. See comments in Photo 11.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 13. Stained soil observed on pit walls/berms will need to be properly cleaned up.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 14. Debris within pit walls/berms.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 15. Colorado Noxious Weed List B (e.g. Canada thistle) observed within the southern pit will need to be managed for.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 16. NFPA placards are peeling, faded, cracked, and/or not legible.

Inspection Photos
Location Name: Wright 1
Location ID: 317118



Photo 18. Wildlife protection equipment needs replacement/repair on partially buried tank.