

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2047 From entrance to location



Photo # 2048 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2049 Location



Photo # 2052 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2053 Debris



Photo # 2066 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2067 Hole in liner/liner needs maintenance



Photo # 2068 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2069 Hole in liner/liner needs maintenance



Photo # 2070 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2071 Hole in liner/liner needs maintenance



Photo # 2072 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2073 Hole in liner/liner needs maintenance



Photo # 2074 Weeds/undesirable plant species

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2075 Weeds/undesirable plant species



Photo # 2076 Weeds/undesirable plant species

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2077 Weeds/undesirable plant species



Photo # 2078 Weeds/undesirable plant species