

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2023

Submitted Date:

06/23/2023

Document Number:

709400297

FIELD INSPECTION FORM

Loc ID 320197 Inspector Name: WOLD, REED On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Regulatory@verdadoil.com	
		MCugnetti@verdadresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202978	WELL	PR	02/01/2018	GW	001-08384	TRACY 1	RI
320197	LOCATION	AC			-	GREAT WESTERN TRACY 1	RI

General Comment:

This is an interim and stormwater inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.

Corrective Action: **Comply with Rule 606.c.**

Date: 06/06/2023

Type

DEBRIS

Comment: Conctere rubble on site next to seperator. (concrete rubble is a prohibited material for use of rip wrap.)

Corrective Action: **Comply with rule 606.d.**

Date: 06/06/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 202978 Type: WELL API Number: 001-08384 Status: PR Insp. Status: RI

Facility ID: 320197 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					

Comment: Erosion on access road and on site from recent rains.

Corrective Action: Comply with Rule 1002.f. Stormwater Management

Date: 06/06/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709400298	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6165669