

Inspection Photos
Location Name: CAERUS PICEANCE LLC N17E Pad
Location #: 334783



Photo # 2087 From entrance to location



Photo # 2088 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N17E Pad
Location #: 334783



Photo # 2089 Location



Photo # 2090 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC N17E Pad
Location #: 334783



Photo # 2091 Location



**Photo # 2093 COUEY 17-14 well missing calibration
info/Meter calibration info not conspicuously posted**



Inspection Photos
Location Name: CAERUS PICEANCE LLC N17E Pad
Location #: 334783



Photo # 2101 Hole in liner/liner needs maintenance



Photo # 2102 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N17E Pad
Location #: 334783



Photo # 2103 Hole in liner/liner needs maintenance



Photo # 2104 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N17E Pad
Location #: 334783



Photo # 2105 Hole in liner/liner needs maintenance



Photo # 2106 Hole in liner/liner needs maintenance

