

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

06/28/2023

Document Number:

679605756

FIELD INSPECTION FORMLoc ID 305408 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8840

Name of Operator: BLUE CHIP OIL INC

Address: 155 E BOARDWALK DR STE 400

City: FORT COLLINS State: CO Zip: 80525

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		bluechipoil@msn.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277282	WELL	PR	02/01/2023	GW	123-22929	JEAN ANN 25-22	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No signage displayed. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/28/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused/disconnected equipment. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	07/28/2023
Type	STORAGE OF SUPL		
Comment:	Unused equipment south of tank battery. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	11/19/2022
Type	TRASH		
Comment:	Wood pallet inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	07/28/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	277282	Type:	WELL	API Number:	123-22929	Status:	PR	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment:									
Corrective Action:									
Date:									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679605197. Only one previous corrective action assigned to this location has been resolved. All previous corrective actions that have not been resolved have been re-assigned to this location with their original corrective action date. One new corrective action was observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Wednesday, June 28, 2023 at approximately 15:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at JEAN ANN 25-22 (Blue Chip Oil Inc.), at location #: 305408 in WELD COUNTY Colorado. While there, I observed a TA wellhead. During this inspection the following possible compliance issues were observed: 1. Trash (wood pallet) inside wellhead fencing. Remove to comply with Rule 606. (Corrective Action Date: July 28, 2023) See attached photo #3. 2. Unused equipment south of tank battery and north of storage shed. Remove to comply with Rule 606. (Corrective Action Date: November 19, 2022) See attached photo #9, 6. 3. Unused equipment on multiple areas of location. Remove to comply with Rule 606. (Corrective Action Date: July 28, 2023) See attached photos #4, 5, 7, 8. 4. No signage displayed at wellhead. Install sign to comply with Rule 605.d. (Corrective Action Date: July 28, 2023) See attached photo #2. It is unknown if the stained soil was treated under the master valve of the wellhead because there is a wood pallet where the stained soil would have been. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	06/28/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403448852	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6164317
679605757	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6164312