

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2023

Submitted Date:

06/30/2023

Document Number:

690204385

FIELD INSPECTION FORM

Loc ID 324832 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 383 INVERNESS PKWY, STE 360
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 9 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213007	WELL	PR	08/14/1987	GW	061-06368	LAS ANIMAS 1-1	RI

General Comment:

On 6/29/2023, Ryan Costa conducted a location inspection.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	The battery sign is faded and too small to see and does not meet the signage requirements. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	06/29/2023
Type	BATTERY		
Comment:	The labeling on the tanks are faded and peeled off. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/29/2023

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume	
Condensate	Tank		
Comment:	There was a dripping condensate leak at the offsite open top tank. Operator was notified the day of inspection for immediate repair.		
Corrective Action:	Immediately Control and contain spills/releases and clean up per Rule 912.a.		Date: 06/29/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	The fence aournd the tanks is missing or inadeuate to prevent livestock entry. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	06/29/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		38.438960,-103.062250
Comment:	The netting on the tank is torn and needs to be repaired. Operator was notified the day of inspection for immediate repair.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 06/29/2023

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			Inadequate
Comment: The berm around the open top tank is insufficient to contain a spill. Corrective action is the day of inspection and the location will remain out of compliance until completed.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: <u>06/29/2023</u>

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1		Open Top		38.438860,-103.069030

Comment: There is no netting to prevent wildlife entry of the open top tank at the wellsite. Operator was notified the day of inspection for immediate install.				
Corrective Action: Install or repair wildlife protection equipment.				Date: <u>06/29/2023</u>

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient		Inadequate
Comment: There are animal burroughsin the secondary containment berm which needs t be repaired. Corrective action is the day of inspection and the location will remain out of compliance until completed.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: <u>06/29/2023</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403451151	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166696
690204386	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6166682