

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2023

Submitted Date:

06/30/2023

Document Number:

690204395

**FIELD INSPECTION FORM**Loc ID 324846 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARMS JASON		jason@strachanexploration.com	
BEAR STACY		stacy@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213098	WELL	PR	05/01/2022	GW	061-06459	STAVELY 1	RI

**General Comment:**

On 6/29/2023, Ryan Costa conducted a location inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	There is unused pipe, cable, and a tank that need to be removed. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	06/29/2023
Type	OTHER		
Comment:	There is oily fluid that has overtopped the containment and spilled out by the pumpjack. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediate clean up. Implement or modify BMPs for improved material handling and spill prevention.	Date:	06/29/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Corrective action is the day of inspection and the location will remain out of compliance until completed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules	Date:	06/29/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3				,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	<input type="text"/>	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		

Comment:	The berm around the tank is insufficient to contain a spill (150% of tank capacity) and has animal boroughs on the sides. Corrective action is the day of inspection and the location will remain out of compliance until completed.	
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date: 06/29/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403451782	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167357">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167357</a>
690204396	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167345">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6167345</a>