

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403452134

Date Received:  
07/03/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>.General</u>		<u>sjninspections@ikavenergy.com</u>
<u>Arthur, Denise</u>		<u>denise.arthur@state.co.us</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203356

Inspection Date: 08/30/2022

FIR Submit Date: 09/06/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 312083

Location Name: Tiffany Number: 5 County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 20 Twp: 33N Range: 6W Meridian: N

Latitude: 37.085058 Longitude: -107.519749

FACILITY - API Number: 05-067-00 Facility ID: 312083

Facility Name: Tiffany Number: 5

Qtrqtr: SWSE Sec: 20 Twp: 33N Range: 6W Meridian: N

Latitude: 37.085058 Longitude: -107.519749

CORRECTIVE ACTIONS:

1  CA# 164350

Corrective Action: Additional topsoil will need to be brought to the location to comply with Rule 1002.b. The topsoil will need to be representative of location salvaged topsoil and free of noxious weeds. Topsoil will need to be properly separated, stored, and stabilized.

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 06/23/2023

An average 6-inches of cover was stripped during the construction of the well site for Tiffany 5-2 and 5-3 new wells from an area of approximately 3.5 acres resulting in over 2800 cu. yds stored on location.

Operator Comment: Average 6 inches x 3.51 acres = 2831.4 cu yds

COGCC Decision: **Not Approved**

COGCC Representative: ECMC Drone aerial calculations of topsoil piles showed that only 1089 cubic feet of topsoil was salvaged and stored at the location. Operator needs to demonstrate with calculations, map, photos, ect., where 2800 cu. yds of topsoil was stockpiled or comply with the Corrective Action.

2  CA# 164352

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)  
BMP's must be installed per good engineer practice.

Date: 09/02/2022

Response: CA COMPLETED

Date of Completion: 10/04/2022

Operator Comment: FIRR #403156739

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed. See attached topsoil completion photos and report.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 7/3/2023 9:40:14 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403452134	FIR RESOLUTION SUBMITTED
403452146	Tiffany 5-2 & 5-3; CA completion photos for topsoil

Total Attach: 2 Files