

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/11/2023

Document Number:

712700382**FIELD INSPECTION FORM**Loc ID 334036 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10755Name of Operator: MORNINGSTAR OPERATING LLCAddress: 400 W 7TH STCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	<a href="#">All SW Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268289	WELL	PR	08/20/2003	CBM	007-06198	SCHUMACHER 32-6 13-1	PR
275732	WELL	PR	03/16/2005	CBM	007-06209	SCHUMACHER 32-6 13-2	PR

**General Comment:**[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Present](#)

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<a href="#">Observed unused equipment on the ground. See Photo #4.</a>		
Corrective Action:	<a href="#">Comply with Rule 606.</a>	Date:	<a href="#">07/26/2023</a>
Type	WEEDS		
Comment:	<a href="#">Extensive growths of weedy species (Russian knapweed) present across the surface lands and upon the exterior of the well location berms.</a>		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	<a href="#">6-ft. chainlink.</a>		
Corrective Action:		Date:	
Type	OTHER		
Comment:	<a href="#">Electrical boxes, cattle panel.</a>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<a href="#">Pipe and hog wire.</a>		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Ancillary equipment	# 4				
Comment:	Electrical boxes				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	Wellhead				
Corrective Action:				Date:	
Type: Flow Line	# 2				
Comment:	2" line from wellhead to separator.				
Corrective Action:				Date:	
Type: Pump Jack	# 2				
Comment:	Heads disassembled, sucker rod sections on ground.				
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:	Electric motor				
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:	3" line from separator to meterhouse. Calibrated within one year.				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		37.022020,-107.444910	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Wells Served By Facilities Above****AirsID**

API Number

API Number

AirsID

007-06198

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 268289 Type: WELL API Number: 007-06198 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/26/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 275732 Type: WELL API Number: 007-06209 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/26/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 18 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Pass			
Ditches	Pass	Gravel	Pass			
Gravel	Pass					
Compaction	Pass					

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700387	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6176144">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6176144</a>
712700391	Well Location Weed Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6176145">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6176145</a>