

# Interim Reclamation and Stormwater Inspection

July 5, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 336152

Inspection Document #: 697504749

Weld County, CO

SENW Section 34 T3N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-VADNEY  
Location ID: 336152



**Photo 1.** Photo taken east of the wellhead, facing South. Photo illustrates an area that is being actively managed for weeds and native perennial vegetation establishment.



**Photo 2.** Photo taken east of the wellhead, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: HSR-VADNEY  
Location ID: 336152



**Photo 3.** Photo taken south of the wellhead, facing South. Photo illustrates an area of Smooth brome establishment (brownish color) with Common rye establishment (yellowish color) to the outer extent.



**Photo 4.** Photo taken west of the wellhead, facing West. Photo illustrates an area of Smooth brome establishment (brownish color), wheatgrass establishment (blueish green color), and Common rye establishment (yellowish color) in the background.





Inspection Photos  
Location Name: HSR-VADNEY  
Location ID: 336152



**Photo 5.** Photo taken west of the wellhead, facing North. See comments under Photo 3.



**Photo 6.** Photo taken from the associated offsite tank battery. Photo illustrates tape that is degrading. Tape and foam coming off piping, which is contributing to trash around the location.

This remains out of compliance and scheduled for repairs.



Inspection Photos  
Location Name: HSR-VADNEY  
Location ID: 336152

Photo 8



**Photo 7.** Photo taken from the associated offsite tank battery. Photo illustrates weed debris around equipment that appears to have blown in from the surrounding area.

This remains out of compliance and scheduled for repairs.



**Photo 8.** Photo taken from the associated offsite tank battery, facing South. Photo illustrates stormwater erosion that is compromising secondary containment.