

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2023

Submitted Date:

07/11/2023

Document Number:

699106906

FIELD INSPECTION FORM

Loc ID 452525 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452525	LOCATION	AC			-	Y34-16 Multi	AC

General Comment:

[Routine Tank Battery Inspection](#)

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Pit by lact is missings placard/ capacity label		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			

Good Housekeeping:			
Type	TRASH		
Comment:	Oily rags around the pit next to the compressor, needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606	Date:	08/31/2023
Type	OTHER		
Comment:	Stained oil around the pit by the compressor. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	08/31/2023

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound walls on sound and west side of location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Air Compressor		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Generators		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Sand Can		
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 5		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	BV CONCRETE		40.089700,-104.531100
Comment:	Pit is missing Placard/ Capacity Label. See attached photo				
Corrective Action:	Install sign to comply with Rule 605.h.			Date:	08/31/2023

Paint

Condition	
Other (Content)	
Other (Capacity)	N/A
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Insufficient	Inadequate	
Comment:	Gap between the ground and the berm. See attached photo				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date:	08/31/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Comment:							
Corrective Action:						Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS
OTHER		1	OTHER	BV CONCRETE			40.089300,-104.531400
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity) 7 BBLs							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficent		Base Sufficient		Adequate
Comment:							
Corrective Action:						Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS
PRODUCED WATER		1	500 BBLs	FIBERGLASS AST			
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Comment:							
Corrective Action:						Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS

PRODUCED WATER	1	OTHER	BV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		40.089800,-104.531100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 452525 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: PR TB

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 7/11/23 at approximately 1124hrs I, Inspector Adam Burns, Conducted an on-site inspection at Shufly Y34-16 Tank Battery of Chevron. Location ID: 452525 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Pit is missing Placard/ Capacity Label. Install sign to comply with Rule 605.h. With a Corrective Action date of 8/31/23 Gap between the ground and the berm. Repair or install berms or other secondary containment devices per Rule 912.d.(1).With a Corrective Action date of 8/31/23 Stained oil around the pit by the compressor. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 8/31/23 Oily rags around the pit next to the compressor, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 8/31/23 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	burnsa	07/11/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106907	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6176749