

## Inspection Photos

Location Name: UPRC-65N64W/23NESE

Location ID: 336587



**Photo #1**

**UPRC-65N64W/23NESE pad 7: Wellsites**

**3: Temporarily Abandoned | TA**

**4: Plugged & Abandoned | PA**



**Photo #2**

**UPV 23-1H4 (123-18886) Wellsite**

**Temporarily Abandoned | TA**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: UPRC-65N64W/23NESE**  
**Location ID: 336587**



**Photo #3**  
**UPRV 23-8H4 (123-18887) Wellsite**  
**Temporarily Abandoned | TA**



**Photo #4**  
**Monfort 24-6H4 (123-18167) Wellsite**  
**Temporarily Abandoned | TA**

**Inspection Photos**  
**Location Name:** UPRC-65N64W/23NESE  
**Location ID:** 336587



**Photo #5**

**UPV 23-1H4, 23-8H4, Monfort 24-6H4** Battery site

**Abandoned: MOST Equipment Removed**

*Formerly served:*

*UPRC 23-9H4, 23-16H4, Chewy B 23-23,*

*Ferguson 24-5H4 ;*

*Plugged & Abandoned | PA*



**Photo #6**

**UPV 23-1H4, 23-8H4, Monfort 24-6H4** Battery site

**Abandoned: MOST Equipment Removed**

**CA: Unnecessary Equipment.**

**2-gas mtr runs, pig station, methanol pump, tank, battery  
signage.**

## Inspection Photos

Location Name: UPRC-65N64W/23NESE

Location ID: 336587



**Photo #7**

**UPV 23-1H4, 23-8H4** Battery site-Prior

**Abandoned: ALL Equipment Removed**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources