

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2023

Submitted Date:

06/26/2023

Document Number:

697602132

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Ahmadian, Alexander 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479608	Flowline System	AC	03/12/2021		-	Facility 4 Consolidation	EI

General Comment:

This is an environmental inspection in response to Spill ID 484634.

Remedial excavation is open. Staining with hydrocarbon odor observed outside the excavation.

No crews were onsite. Any corrective actions from previous inspections or forms that have not been addressed are still applicable. Photos are attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action:

Date: 07/03/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Orange construction fencing is adequate around the excavation.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Staining with strong hydrocarbon odor was observed outside of the excavation on the soil. Several spots were observed 10-20 feet north of the excavation.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, groundwater and surface water as soon as the impacts are discovered.

Date: 06/29/2023

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment		All stockpiled contaminated soil has been removed from the location.		
Corrective Action				Date: _____

Spill/Remediation:

Comment: Remedial excavation is open with staining observed within and outside the excavation.

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment

User

Date

Spill location is in close proximity to residential neighborhood.

ahmadiiaa

06/26/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602133	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6177031