

Inspection Photos

7/10/2023

Operator: GUNNISON ENERGY LLC - 10515

Location Number: 324485

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 1: Photos 1-2 taken from the North end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 2: See comments under photo 1. Photos also show areas on the west end of the Location, not needed for production, have not been reclaimed in accordance with 1003 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485



Photo 3: Photos taken from the northwest corner of the Location, facing east and south. Photos show areas on the west end of the Location, not needed for production, have not been reclaimed in accordance with 1003 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485



Photo 4: Photo shows Well API #051-06126. Well is the easternmost producing well on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 5: Photo shows Well API #051-06075. Well is the westernmost producing well on the Location; “As Drilled” coordinates within scout card incorrect. Photo right shows wildlife protection BMP (chicken wire/netting) is no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 6: Continue from photo 5. Photo a Google Earth aerial image of the Location. Photo shows well coordinates from the Scout Cards; as drilled coordinates for Well API 051-06075 incorrect; coordinates for the abandoned Well API 051-06122 also incorrect.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485



Photo 6: Photo taken from the tank battery facility on the east end of the Location. Photo shows tank battery signage missing required information in accordance with Rule 605.e; The four tanks at the battery facility observed missing required information in accordance with Rule 605.h.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 8: Photos 8-7 show various unused equipment/trash/debris observed improperly stored within the battery's containment BMP.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485



Photo 9: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485



Photo 10: Photo taken from the east end of the Location. Photo shows Unused equipment stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 11: Photos taken from the slopes on the north end of the Location. Hydromulch observed on slopes, though degradation of the BMP is beginning to occur. Maintenance advised prior to failure of the control.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 12: Photos taken from cut slopes on the east end of the Location. Hydromulch observed on slopes, though degradation of the BMP is beginning to occur. Maintenance advised prior to failure of the control. Photo right also shows Undesirable/Noxious Plant Species (Bindweed, white flowers) established on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 13: Photos 13-16 show Undesirable and Noxious Plant Species observed established on the vegetated areas along the perimeter of the Location, and the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485




Photo 14: See comments under photo 13.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485




Photo 15: See comments under photo 15.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location Number: 324485



Photo 16: Photo taken from the east end of the Location. Photo shows Unused equipment stored on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location Number: 324485



Photo 17: Photos taken from the sediment trap inlet on the southwest end of the Location. Photo shows the gully erosion has been repaired, and the inlet armored with riprap material; liner appears to have been placed beneath the rock material.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources