

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	stained soil in a few spots on location		
Corrective Action:	Comply with Rule 606	Date:	07/18/2023
Type	WEEDS		
Comment:	weeds are beginning to grow tall inside of the location fencing		
Corrective Action:	Comply with Rule 606	Date:	07/18/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	plain wire on 3 sides (electric?)		
Corrective Action:		Date:	
Type	OTHER		
Comment:	ancillary equip/ fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box and transformers		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241394 Type: WELL API Number: 123-09183 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/25/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: This location does not comply with Rule 1002.c. Sediment laden storm water has Discharged sediment off location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/14/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On Tuesday 7-11-2023 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Just Unit 2 API #05-123-09183 County: Weld Weather: Clear/hot. Location: Dry. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 1002..(2).D : Stained soil in a few spots on location, CA date 7-18-2023. 1002.f.(2)C: Storm water has discharged sediment off of location, CA date 7-14-2023 606: Weeds are growing tall inside location fencing, CA date 7-18-2023. See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with CECMC rules.</p>	revasr	07/11/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402071	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6177432