

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

07/15/2023

Document Number:

698600726

FIELD INSPECTION FORMLoc ID 303532 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 38 PALMER CREST CT

City: SPRING State: TX Zip: 77381

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253249	WELL	PR	09/18/1986	GW	125-07126	T. BROPHY 46-15	PR

General Comment:

Work Over Rig work and routine site inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track road off maintained county road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign at remote Gas Meter Run on CR 57.		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:	Rig sign posted at intersection of CR 57 and lease access road.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact number posted on both well signs.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote, located off CR 57.		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack power and control panel.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead. Rods and tubing currently removed as part of clean out work but will be tripped back into wellbore. Valves at wellhead currently closed for work over.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Meter House. Remote, located off CR 57.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253249	Type:	WELL	API Number:	125-07126	Status:	PR	Insp. Status:	PR
Workover									
Comment:		Excell Services Rig #5 currently on well. Clean out work on wellbore and hydro static testing of tubing string. Rig sign posted at CR. Sucker rods and tubing string out of the well and crew is tripping tubing back into wellbore hydro static testing tubing string for holes. Site is safe, clean, and orderly as expected. Satisfactory Inspection.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600754	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182350