

**Inspection Photos**  
**Location Name: Brophy J 26-15**  
**Location ID: 125-07570**



**1. Well sign at well site.**



**2. View of wellhead. Note stained soils in lower left of picture.**



**Inspection Photos**  
**Location Name: Brophy J 26-15**  
**Location ID: 125-07570**



**3. Casing flowline off west side of wellhead with visible soil staining.**



**4. Soils areas that are dry with visible cracks and what appears to be unstained soil below.**



**Inspection Photos**  
**Location Name: Brophy J 26-15**  
**Location ID: 125-07570**



**5. Overview of stained soil to the south and west outside the stock panel fencing that surrounds the well site.**



**6. View of Pump Jack. Note staining in lower right portion of picture.**

**Inspection Photos**  
**Location Name: Brophy J 26-15**  
**Location ID: 125-07570**



**7. Overview of well site looking North. Staining visible at center of photo.**



**8. Well sign at remote Gas Meter Run.**



**Inspection Photos**  
**Location Name: Brophy J 26-15**  
**Location ID: 125-07570**



**9. View of remote meter site off CR 57.**



**10. View of gas meter run inside meter shed.**

