

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2905 From entrance to location



Photo # 2906 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2907 Location



Photo # 2908 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2911 Debris

Photo # 2912 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434




Photo # 2915 Debris

Photo # 2917 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2918 Debris



Photo # 2916 Wellhead sign missing API # & Stained soils & gravel near wellhead

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2908 Multiple wellhead signs missing API #



Photo # 2906 Battery sign missing well API #'s

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2920 Wellhead sign missing API #



Photo # 2922 Wellhead sign missing API #

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 13-19 Pad

Location ID: 335434



Photo # 2923 Wellhead sign missing API #

Photo # 2924 Wellhead sign missing API #