

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad

Location ID: 335382



Photo # 3021 From entrance to location



Photo # 3022 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad

Location ID: 335382



Photo # 3023 Location



Photo # 3024 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad

Location ID: 335382



Photo # 3025 Location



Photo # 3035 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad

Location ID: 335382



Photo # 3036 Open ended load line




Photo # 3041 Tank label missing required information





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad

Location ID: 335382



Photo # 3042 Wellhead sign missing API #



Photo # 3043 Wellhead sign missing API #



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad

Location ID: 335382



Photo # 3046 Debris



Photo # 3024 Battery sign missing API #'s