

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2023

Submitted Date:

07/15/2023

Document Number:

708901049

**FIELD INSPECTION FORM**Loc ID 335382 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

37 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265413	WELL	PR	12/01/2004	OW	045-09009	FEDERAL RWF 334-19	PR
265415	WELL	PR	11/17/2003	OW	045-09011	FEDERAL RMV 171-19	PR
273336	WELL	PR	12/01/2018	GW	045-10238	FEDERAL RWF 434-19	PR
273337	WELL	PR	03/07/2005	GW	045-10237	FEDERAL RWF 534-19	PR
300169	WELL	PR	06/30/2010	GW	045-17853	FEDERAL RWF 431-30	PR
300171	WELL	PR	03/31/2010	GW	045-17852	FEDERAL RWF 331-30	PR
300172	WELL	PR	03/31/2010	GW	045-17851	FEDERAL RWF 31-30	PR
300174	WELL	PR	03/31/2010	GW	045-17850	FEDERAL RWF 332-30	PR
300176	WELL	PR	03/31/2010	GW	045-17849	FEDERAL RWF 32-30	PR
300177	WELL	PR	03/31/2010	GW	045-17848	FEDERAL RWF 531-30	PR
412993	WELL	PR	02/01/2011	GW	045-18707	FEDERAL RWF 644-19	PR

**General Comment:**

CECMC Inspection Report Summary

On 07/14/2023 at approximately 09:43 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC FEDERAL RMV 171-19 Pad.  
Location # 335382 in Garfield County Colorado.  
Location is within High Priority/Density Habitat areas.  
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Multiple wellhead signs missing required information with a CA date of 09/13/2023
2. Signs/Marker - Tank label missing required information with a CA date of 09/13/2023
3. Signs/Marker - Battery sign missing required information with a CA date of 09/13/2023
4. Open ended load line with a CA date of 07/22/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign missing well API #'s		
Corrective Action:	Comply with Rule 605/add required information	Date:	09/13/2023
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Multiple wellhead signs missing API #		
Corrective Action:	Comply with Rule 605/add required information	Date:	09/13/2023
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing required information		
Corrective Action:	Comply with Rule 605/add required information	Date:	09/13/2023
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:	Pressure transducers & Taylor plugs located on all bradenhead, all bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	All load lines will be capped or plugged	Date:	07/22/2023
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,

Comment:	Centralized containment
Corrective Action:	Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	265413	Type:	WELL	API Number:	045-09009	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	265415	Type:	WELL	API Number:	045-09011	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	273336	Type:	WELL	API Number:	045-10238	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	273337	Type:	WELL	API Number:	045-10237	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	300169	Type:	WELL	API Number:	045-17853	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	300171	Type:	WELL	API Number:	045-17852	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	300172	Type:	WELL	API Number:	045-17851	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	300174	Type:	WELL	API Number:	045-17850	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Facility ID:	300176	Type:	WELL	API Number:	045-17849	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Facility ID:	300177	Type:	WELL	API Number:	045-17848	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Facility ID:	412993	Type:	WELL	API Number:	045-18707	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none
Rip Rap						
Berms						
		Compaction				Light compaction in some sections
				Material Handling And Spill Prevention		Chemical tank containment
Sediment Traps						
		Gravel				Sparse
		Ditches				
Check Dams						
		Other				Hay bales
		Waddles				
		Rip Rap				
		Culverts				
Ditches						
Drains						
Compaction						Light compaction

Comment: Small amount of erosion in multiple spots S/SE edge of pad.

Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Signs/Marker & Equipment for observed compliance issues.	smelserw	07/15/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901050	Inspection 708901049 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182476">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182476</a>
708901051	Inspection 708901049 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182477">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182477</a>