

**Inspection Photos**  
**Location Name: Bledsoe 15-7-3-43**  
**Location ID: 125-09117**



**1. Well sign at well site located inside stock panel fencing.  
Noted vegetation growth inside fenced area.**



**2. Overview of well site.**

**Inspection Photos**  
**Location Name: Bledsoe 15-7-3-43**  
**Location ID: 125-09117**



**3. Wellhead.**



**4. Meter/Separator building with door open and Vertical Separator visible.**



**Inspection Photos**  
**Location Name: Bledsoe 15-7-3-43**  
**Location ID: 125-09117**



**5. Meter/Separator building with door open and Gas Meter Run visible.**



**6. Chart inside meter box dated 12-2-22 at time of inspection.**

**Inspection Photos**  
**Location Name: Bledsoe 15-7-3-43**  
**Location ID: 125-09117**



**7. Prime Mover has been removed from Pump Jack. Note surrounding vegetation growth.**



**8. View of erosion channel looking from location entry area to the SE down access road.**



**Inspection Photos**  
**Location Name: Bledsoe 15-7-3-43**  
**Location ID: 125-09117**



**9. Closer view of erosion channel looking from location entry area to the SE down access road.**



**10. View of area where access road has washed out and erosion channel turns in more E direction carrying sediment down the sloping grade.**



**Inspection Photos**  
**Location Name: Bledsoe 15-7-3-43**  
**Location ID: 125-09117**



**11. View of erosion channel flowing east down grade.**



**12. View of sediment plume as flow reaches bottom of sloping grade.**