

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2023

Submitted Date:

07/16/2023

Document Number:

698600733

FIELD INSPECTION FORM

Loc ID 304945 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 2501 HARWOOD ST STE 1238
City: DALLAS State: TX Zip: 75201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Fisher, Jeremy	970-520-8433	Jeremy_Fisher@omimexgroup.com	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276975	WELL	PR	11/01/2021	GW	125-09180	BLEDSOE 5-17-3-43	PR

General Comment:

[Routine Inspection.](#)

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on well sign.		Date:
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation growth inside stock panel fencing. Not complete coverage at time of inspection but will require treatment or clean up.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock Panel Fencing.		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Meter/Separator Shed.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing valve closed. Tubing valve closed.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Located 4 Deadmen. All 4 have markers but 2 are down.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Concrete Pump Jack slab.		

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Located inside Meter/Separator Shed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Located inside Meter/Separator Shed. Chart in Meter Box dated 12-2-22.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 276975 Type: WELL API Number: 125-09180 Status: PR Insp. Status: PR

Producing Well

Comment: Well appears to be Shut In with wellhead casing valve closed and tubing valve closed. Gas meter chart in meter box is dated 12-2-22. Electronic well file reflects last reported production as 8/1/2022.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 08/16/2023

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600761	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182786