

Inspection Photos  
Location Name: Bledsoe 15-18-3-43  
Location ID: 125-09004



1. Wellhead sign inside fencing.



2. View of wellhead with polish rod visible.

**Inspection Photos**  
**Location Name: Bledsoe 15-18-3-43**  
**Location ID: 125-09004**



**3. Closer view of wellhead. Concrete Pumping Unit Slab in the background.**



**4. View of Gas Meter Run and Vertical Separator shed.**

**Inspection Photos**  
**Location Name: Bledsoe 15-18-3-43**  
**Location ID: 125-09004**



**5. View of Concrete Pad, Dryer Vessel, Pipe Section, and Debris inside fencing.**



**6. Pump Jack Rail propped up at Gas Meter/Separator Shed.**

**Inspection Photos**  
**Location Name: Bledsoe 15-18-3-43**  
**Location ID: 125-09004**



**7. Pumping Unit rails and guards inspector picked up outside the fencing and propped up against panel fencing.**



**8. Surface casing valve open to atmosphere.**

Inspection Photos  
Location Name: Bledsoe 15-18-3-43  
Location ID: 125-09004



9. View of Stuffing Box.



10. Gas is venting through Compression Bolt.

**Inspection Photos**  
**Location Name: Bledsoe 15-18-3-43**  
**Location ID: 125-09004**



**11. View of Chart dated 12-2-22 that was in Meter Box at time of inspection.**



**12. View of 1 of 4 anchors and marker.**