

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/12/2023

Document Number:

696205088

FIELD INSPECTION FORMLoc ID 424290 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Gunnison		GEOps@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421193	CENTRALIZED EP WASTE MGMT FAC	AC	01/18/2011		-	HOTCHKISS WATER STORAGE FACILITY 421193	RI
424290	LOCATION	AC			-	HOTCHKISS WATER STORAGE FACILITY	RI
454880	PIT	AC			-	HWSF-Southern Pit	RI
454881	PIT	AC			-	HWSF-Northern Pit	RI

General Comment:

On 7/10/2023, Reclamation Specialist Trujillo inspected Gunnison Energy LLC's Hotchkiss Water Storage Facility location in Gunnison County, Colorado

This inspection is a followup to #696204292 to document compliance with the following corrective actions:

- Stormwater
- Good Housekeeping
- Fence in disrepair

It was observed that the Location remains out of compliance with ECMC Rules and Corrective Actions.

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Previous inspection observed various unused trash/debris/equipment stored on the Location.</p> <p>It was observed in this inspection that trash/debris/unused equipment remains improperly stored on the Location.</p> <p>CA has not been addressed and remains applicable.</p> <p>Operator appears to have conducted work along the perimeter stormwater ditch- liner material previously within ditch observed appears to have been ripped out, and is now considered debris.</p>		
Corrective Action:	Comply with Rule 606.	Date:	11/01/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>421193</u>	Type:	<u>CENTRALIZE</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>424290</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>454880</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>454881</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection observed BMPs to manage runoff and minimize erosion/degradation are missing or insufficient at the access road, at the Location entrance- erosion degradation evident.

Degradation has been repaired.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Multiwell Reuse/ Recycling Lined: YES Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: HDPE Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Netting/Fence com

Fencing Condition: Inadequate

Previous inspection observed that the lower mesh/wire fence was in disrepair at both pits; sections of netting/fence observed lifted off the ground. Inspection required Operator to maintain fencing.

Comment: It was observed in this inspection that the lower mesh/wire fence at base of netting remains in disrepair, sections of netting/fence remain lifted of the ground. Tears/holes were also observed within the netting.

CA has not been addressed and remains applicable.

Corrective Action

Date: 11/19/2022

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403461770	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6178184
696205089	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6178180