

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2023

Submitted Date:

07/19/2023

Document Number:

707601528

FIELD INSPECTION FORM

Loc ID 305789 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424433	WELL	TA	06/30/2022	OW	123-34031	Orr USX A03-15D	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing: Balanced plug.
Battery: Abandoned.
Abandoned Battery SE corner GPS coordinates: 40.511042 / -104.530028
Well GPS coordinates: 40.514150 / -104.533350

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 424433 Type: WELL API Number: 123-34031 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: A-Plus Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2553'-2421' Cement Volume (sx): 10 sxs

Good Return During Job: _____ Cement Type: Class "G" Neat 15.8#

Comment: **Workover Contractor: A-Plus Well Services, Rig #12.**
Cement Contractor: A-Plus Well Services.

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 05/15/2023. Approved.
 Form 17 Brhd test on file. Date: 07/17/2023. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 07/18/2023. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 07/18/2023. Approved.

2023/18/18:
 Plugging Operations: Cementing: Balanced plug.
 2023/07/18: JSA attached as photo to this report.

SAFETY/JSAMEETING, CHECK PSI, CSG O PSI, TBG O PSI, SURFACE O PSI, TOOH LD 124 JTS OF TBG, RUWL, PU AND SET A 4.5 11.6# 10K CIBP AT 2553, RDWL, TIH W,'00
JTS TO 2553, , TEST PUMP LINES, PUMP BALANCE PLUG AS FOLLOWS, PUMP 10 BBLS CHEM WASH AND 20 BBLS FRESH WATER, 10 SACS OR 2 BBLS OF 15.8# G-NEAT
CMT @1.15 YIELD, DISPLACE 9.3 BBLS FRESH WATER, EST CMT 2553-2421, TOOH 34 JTS, REVERSE CIRCULATE AT 1486 W/20 BBLS, TOOH LD 48 JTS, PERFORM BUBBLE/FLOW CHECK AS PER SOP FOR 30 MIN, CSG HAD NO BUBBLES/FLOW, SURFACE HAD NO BUBBLES/FLOW.RUWL, PU 4.5 11.6# JET CUTTER AND CUT CSG AT 1029, RDWL, NDWH AND SURFACE, UN-LAND CSG, NU BOP, SWI.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> Date: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On TUE 07/18/2023 at approximately 16:10 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Orr USX/A03-15D Location ID: 305789 Well Name(s): Orr USX A03-15D. API: 123-34031. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing: Balanced plug. Battery: Abandoned. Abandoned Battery SE corner GPS coordinates: 40.511042 / -104.530028 Well GPS coordinates: 40.514150 / -104.533350</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/19/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601529	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6186613