

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 306542

Inspection Document #: 701900953

SENE Section 5 T3N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Becker 12-10i
Location ID: 306542



Photo 1. 2022 aerial imagery of the well pad, access road and associated tank battery (north is up).

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 2. Overview photos of the well pad access road (left) and well pad (right) taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad and access show significant bare ground and do not appear consistent with adjacent reference area (see photo #5).

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 5. Reference area.

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 6. Overview photo of the tank battery taken from the western edge facing east.

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 7. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Becker 12-10i
Location ID:306542



Photo 8. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: germination of desirable species observed at location. 80% vegetation cover has not yet been achieved, site will remain in-process until rule 1004 standards are met.