

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2023

Submitted Date:

07/20/2023

Document Number:

707601530

FIELD INSPECTION FORM

Loc ID 305789 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424433	WELL	TA	06/30/2022	OW	123-34031	Orr USX A03-15D	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing: Surface plug.
Battery: Abandoned.
Abandoned Battery SE corner GPS coordinates: 40.511042 / -104.530028
Well GPS coordinates: 40.514150 / -104.533350

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 424433 Type: WELL API Number: 123-34031 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: A-Plus Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 2421'-1029'-0' Cement Volume (sx): 350 sxs

Good Return During Job: YES Cement Type: Class "G" Neat 15.8#

Comment: [Workover Contractor: A-Plus Well Services, Rig #12.](#)
[Cement Contractor: A-Plus Well Services.](#)

Reference:
 Form 6N on file. Notice of Intent to Abandon date: 05/15/2023. Approved.
 Form 17 Brhd test on file. Date: 07/17/2023. Approved.
 Form 42 on file. Notice of MIRU. Start Date: 07/18/2023. Approved.
 Form 42 on file. Notice of Plugging Operations. Start Date: 07/18/2023. Approved.

2023/07/19:
 Plugging Operations: Cementing: Balanced plug.
 2023/07/19: JSA attached as photo to this report.

SAFETY/JSAMEETING, CHECK PSI, CSG O PSI, SURFACE O PSI, CONDITION HOLE W/10 BBLSCHEM WASH AND 70 BBL FRESH WATER, TOOHL 24JTSOF 4.5 11.6# M-80 CSG, CHANGE OVER TOOLS, TIH W/33 JTS AND 1 6FT SUB OF TBG TO 1029, TEST PUMP LINES, PUMP BALANCE PLUG AS FOLLOWS, PUMP 10 BBLSCHEM WASH, 115 SACS OR 23.5 BBLSO 15.8# G-NEAT CMT @1.15 YIELD, DISPLACE 2.7 BBL FRESH WATER, EST CMT 1029-707, TOOHL SB22 JTS AND LD 11 JTS AND 1 6FT SUB, WOC 4HR, TIH AND TAG TOP OF CMT AT 744 W/24JTS, TEST PUMP LINES, PUMP SURFACE PLUG AS FOLLOWS, 10 BBL CHEM WASH, 235 SACS OR 48 BBLSO 15.8# G-NEATCMT @1.15 YIELD, CMT RETURNS AT SURFACE, EST CMT 744 TO SURFACE, TOOHL 24 JTS. NDBOP, MUWH. TOP OFF CMT, SWI.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> Date: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 07/19/2023 at approximately 15:54 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Orr USX/A03-15D Location ID: 305789 Well Name(s): Orr USX A03-15D. API: 123-34031. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing: Surface plug. Battery: Abandoned. Abandoned Battery SE corner GPS coordinates: 40.511042 / -104.530028 Well GPS coordinates: 40.514150 / -104.533350</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601531	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189078