

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3NENE

Location ID: 334596

Date: 7/6/2023



Location Entrance – Photo #05036



North Side of Location – Photo #05037

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3NENE

Location ID: 334596

Date: 7/6/2023



Wellheads – Photo #05038



Separators – Photo #05041

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3NENE

Location ID: 334596

Date: 7/6/2023



Tank Battery – Photo #05045



Unsecured Hatch on Separator – Photo #05042

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3NENE

Location ID: 334596

Date: 7/6/2023



**Unsecured Hatch on Separator – Photo #05043**



**Lack of Stabilization – Photo #05044**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3NENE

Location ID: 334596

Date: 7/6/2023



Administrative BMP – Photo #05048

Lack of Stabilization on Access Road – Photo #05049

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/3NENE

Location ID: 334596

Date: 7/6/2023



**Lack of Stabilization on Access Road – Photo #05050**

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05051**