

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Mechanical Conditions. Per rule 608.e		
Corrective Action:	Compressor is re acurring on going down due to overheating and is now a issue. Equipment need to be fixed or replaced.	Date:	08/25/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 463929 Type: WELL API Number: 123-50129 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
This is in reference to Complaint filed on 7-18-23 Document #403469172	sernaa	07/21/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698705122	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6190464