

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



Photo 1 – Spill ID 481679 excavation. Fencing is falling down around open excavation. Soil stored on location with inadequate BMPs.

Photo 2 – Flowline excavation for Rem 26277. Fencing is down around open excavation. Soil stockpile has missing/inadequate BMPs.

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



Photo 3 – Flowline excavation for Rem 26277. Fencing is down around open excavation. Soil stockpile has missing/inadequate BMPs.

Photo 4 – Flowline excavation for Rem 26277. Fencing is down around open excavation. Soil stockpile has missing/inadequate BMPs. Weeds on access road for API 05-123-09913.

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



**Photo 5 – Flowline excavation for Rem 26277.
Fencing is down around open excavation.**

**Photo 6 – Flowline excavation for Rem 26277.
Fencing is down around open excavation.**

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



Photo 7 – Flowline excavation for Rem 26277. Fencing is down around open excavation. Soil stockpile has missing/inadequate BMPs.

Photo 8 – Flowline excavation for Rem 26277. Fencing is down around open excavation. Soil stockpile has missing/inadequate BMPs.

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



**Photo 9 – Flowline excavation for Rem 26277.
Fencing is down around open excavation.**

**Photo 10 – Flowline excavation for Rem 26277.
Fencing is down around open excavation.**

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



**Photo 11 – Flowline excavation for Rem 26277.
Fencing is down around open excavation.**

**Photo 12 – Flowline excavation for Rem 26277.
Fencing is down around open excavation. Weeds on
access road for API 05-123-09913.**

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



**Photo 13 – Flowline excavation for Rem 26277.
Fencing is down around open excavation. Soil
stockpile has missing/inadequate BMPs.**

**Photo 14 – Flowline excavation for Rem 26277.
Fencing is down around open excavation.**

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



Photo 15 – Wellhead (API 05-123-09913) excavation for Rem 26277. Fencing is down around open excavation. Trash and debris (concrete, rebar, etc.) piled near open excavation.

Photo 16 – Wellhead (API 05-123-09913) excavation for Rem 26277. Fencing is down around open excavation. Trash and debris (concrete, rebar, etc.) piled near open excavation. Weeds growing in open excavation. Soils pile with no BMPs present next to open excavation.

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



Photo 17 – Soils pile with no BMPs present next to open wellhead excavation.

Photo 18 – Weeds on access road for API 05-123-09913.

Inspection Photos
UPRR 43 PAN AM I 33 & 27
Spill ID 481679
Remediation Project Nos 26277, 23488



Photo 19 – Weeds on access road for API 05-123-09913.



Photo 20 – Orange excavation fencing has become trash.