

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2023

Submitted Date:

07/15/2023

Document Number:

698600729

**FIELD INSPECTION FORM**Loc ID 303842 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 38 PALMER CREST CT

City: SPRING State: TX Zip: 77381

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253692	WELL	PR	10/15/1996	GW	125-07570	J. BROPHY 26-15	PR

**General Comment:**

Routine Inspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained CR.			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	OTHER			
Comment:	Well sign located at remote gas meter run.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Emergency contact information posted on both the well site and remote gas meter run signs.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	Inspector observed stained soil at well site. Staining appears to be a thin layer located at the surface as areas that dried and cracked appear to have no staining below the visible surface. Observed staining pattern appears to possibly be emanating from casing flowline T connection from below grade. There are two triangle like patterns visible, one to the south of the T connection and one to the west of the T connection. From the T connection to the south staining is approximately 18 feet in length, 12-18 inches at the T connection, and widening to 8-9 feet at the base. To the west of the T connection staining is approximately 8-9 feet in length, 18 – 30 inches at the top, and 4-5 feet at the base. See Inspection Photo Log.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Corrective action date adjusted to reflect FIR submission date due to computer and software issues.			Date: 08/16/2023
In Containment: No				
Comment:	Heavy soaking rains associated with the on going weather pattern may have contributed to collection of organic material and algae growth in standing water. The observed relationship between wet/damp soil and casing flowline dictates investigation to ensure flowline integrity.			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Stock panel fencing.			
Corrective Action:			Date:	
<b>Equipment:</b>				
Type: Other	# 1			corrective date
Comment:	Meter Shed. Remote, located off CR 57.			
Corrective Action:				Date:
Type: Bradenhead	# 1			

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote, located off CR 57.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Casing valve open. Tubing valve closed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack power and control panel.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253692	Type:	WELL	API Number:	125-07570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Casing valve open. Tubing valve closed. Gas meter run valves open.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403465562	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182388">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182388</a>
698600757	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182385">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182385</a>