

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2023

Submitted Date:

07/16/2023

Document Number:

698600736

FIELD INSPECTION FORM

Loc ID 304900 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 2501 HARWOOD ST STE 1238
City: DALLAS State: TX Zip: 75201

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Chambers, Kit		Kchambers@ravenwoodlabs.com	
Quint, Craig		craig.quint@state.co.us	
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275918	WELL	PR	03/01/2022	GW	125-09119	BLEDSOE 11-18-3-43	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Located inside stock panel fencing.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on Well sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Vegetation growth inside stock panel fencing. Not complete coverage at time of inspection but will require treatment or clean up.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Stock Panel Fencing.		
Corrective Action:			Date:
Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Currently not connected to well.		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas Motor.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Chart in Meter Box dated 12-2-22.		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Meter/Separator Shed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump Jack Concrete Slab.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing valve closed. Tubing pulled 10' above well and ball valve installed, valve closed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 275918 Type: WELL API Number: 125-09119 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Casing valve closed. Tubing valve closed. Well appears to be Shut In as reported 8/1/22. Gas meter chart is dated 12-2-22 at time of inspection. Electronic well file reflects last reported production status is 8/1/2022

Corrective Action: **Submit required Form 7(s) to COGCC per rule 413.** Date: 08/16/2023

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403465630	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182822
698600765	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182821