

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Location Overview: Location is within High Priority/Density  
Habitat areas & within close proximity to Bald Eagle Roost  
site. Drainage contributes to the Colorado River.**

**Section/Township/Range: 21 6S94W**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**





**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Photo # 4639 From Inspection 708900241 conducted on 04/07/2023 Erosion & transport of sediment off lease road/insufficient BMP's**



**Photo # 3488 Erosion & transport of sediment off lease road/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Photo # 4640 From Inspection 708900241 conducted on 04/07/2023 Erosion & transport of sediment off lease road/insufficient BMP's**



**Photo # 3495 Erosion & transport of sediment off lease road/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Photo # 3490 Erosion & transport of sediment off lease road/insufficient BMP's**



**Photo # 3492 Erosion & transport of sediment off lease road/insufficient BMP's**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Photo # 3493 Erosion & transport of sediment off lease road/insufficient BMP's – sediment is being transported into a vegetated area & choking off vegetation.**



**Photo # 3494 Erosion & transport of sediment off lease road/insufficient BMP's – sediment is being transported into a vegetated area & choking off vegetation.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Photo # 3502 Erosion & transport of sediment off lease road/insufficient BMP's – sediment is being transported into a vegetated area & choking off vegetation.**



**Photo # 3500 Erosion & transport of sediment off lease road/insufficient BMP's – sediment is being transported into a vegetated area & choking off vegetation.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 32-21 pad**  
**Location ID: 323916**



**Photo # 3501 Erosion & transport of sediment off lease road/insufficient BMP's – sediment is being transported into a vegetated area & choking off vegetation.**