

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/13/2023

Submitted Date:

07/23/2023

Document Number:

698600742

**FIELD INSPECTION FORM**

Loc ID 303314 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 38 PALMER CREST CT  
City: SPRING State: TX Zip: 77381

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112724	PIT	AC	08/18/2020		-	BROWN 13-1	AC
252889	WELL	PR	06/08/1982	GW	125-06765	BROWN 13-1	PR

**General Comment:**

[Routine Inspection.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained county road.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Located on Meter Shed inside fencing.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information posted on well sign.		Date: _____
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Vegetation growth around pit banks.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Dried vegetaion debris noted trapped along inside and outside of fencing.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Stock Panel Fencing.		
Corrective Action:		Date:	
Type	PIT		
Comment:	Combination of wire and stock panel fencing.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Digital Meter System.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas Dryer Vessel.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Stell Meter Shed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 112724 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 252889 Type: WELL API Number: 125-06765 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Rods and tubing in wellbore. Tubing valve open. Casing valve open. Meter run valves open.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Evaporation                  Lined: NO                  Pit ID: 112724                  Lat: 40.060243                  Long: -102.464260

Reference Point: SE                  Other:                   Length: 30                  Width: 20

**Lining:**

Liner Type: Other                  Liner Condition:

Comment: Unlined.

Corrective Action:

Date:

**Fencing:**

Fencing Type: Livestock                  Fencing Condition: Adequate

Comment: Vegetation debris noted trapped inside and outside fencing.

Corrective Action:

Date:

**Netting:**

Netting Type:                   Netting Condition:

Comment: None.

Corrective Action:

Date:

Anchor Trench Present: NO                  Oil Accumulation: NO                  2+ feet Freeboard: YES

Comment:

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600780	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6191993">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6191993</a>