

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2023

Submitted Date:

07/17/2023

Document Number:

698600738**FIELD INSPECTION FORM**Loc ID 304948 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 2501 HARWOOD ST STE 1238City: DALLAS State: TX Zip: 75201**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------------|-------|----------------------------------|------------------|
| Chambers, Kit | | Kchambers@ravenwoodlabs.com | <u>7/16/2023</u> |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| McGlaughlin, Dennis | | Dmac@ravenwoodlabs.com | <u>7/16/2023</u> |
| Quint, Craig | | craig.quint@state.co.us | |
| , Engineering | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 276980 | WELL | PR | 12/01/2021 | GW | 125-09183 | BLEDSE 16-18-3-43 | PR |

General Comment:Routine Inspection.

| Location | | | | | |
|--|--|--------|--|--|------------------|
| Lease Road: | | | | | |
| Type | Access | | | | |
| comment: | Two track off maintained county road. | | | | |
| Corrective Action | L | | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | | |
| Signs/Marker: | | | | | |
| Type | WELLHEAD | | | | |
| Comment: | Located inside stock panel fencing. | | | | |
| Corrective Action: | | | | | Date: |
| Emergency Contact Number: | | | | | |
| Comment: | Posted on well sign. Attempts to contact Operator at 1-877-425-4882 failed. Number dials but call ends with hang up and no answer. | | | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | | | | Date: 08/16/2023 |
| Good Housekeeping: | | | | | |
| Type | WEEDS | | | | |
| Comment: | Vegetation growth inside stock panel fencing. Not complete coverage at time of inspection but will require treatment or clean up. | | | | |
| Corrective Action: | | | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | | |
| Spills: | | | | | |
| Type | Area | Volume | | | |
| In Containment: No | | | | | |
| Comment: <input type="text"/> | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |
| Fencing/: | | | | | |
| Type | PUMP JACK | | | | |
| Comment: | Stock Panel Fencing. | | | | |
| Corrective Action: | | | | | Date: |
| Equipment: | | | | | |
| | | | | | corrective date |
| Type: Other | # 1 | | | | |
| Comment: | Meter/Separator Shed | | | | |
| Corrective Action: | | | | | Date: |
| Type: Vertical Separator | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Ancillary equipment | # 1 | | | | |
| Comment: | Wellhead. Surface casing valve is open to atmosphere. Casing valve closed. Tubing valve closed. | | | | |
| Corrective Action: | Close well to atmosphere as directed by Rule 434.b.(1) | | | | Date: 07/18/2023 |
| Type: Prime Mover | # 0 | | | | |

| | | | | |
|--------------------------|-----------------------------------|--|-------|--|
| Comment: | Removed. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Pump Jack | # 1 | | | |
| Comment: | Currently disconnected from well. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Concrete Pumping Unit Slab. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Chart in Meter Box dated 12-2-22. | | Date: | |
| Corrective Action: | | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|------------|
| Yes/No | YES | | |
| Comment: | Gas is actively venting around packing at the wellhead cap. Inspector attempted to contact Operator but number provided on well sign does not complete call. | | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | Date: | 07/19/2023 |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 276980 | Type: | WELL | API Number: | 125-09183 | Status: | PR | Insp. Status: | PR |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| <u>Comment:</u> Casing valve closed. Tubing valve closed. Well appears to be Shut In. Gas meter chart is dated 12-2-22 at time of inspection. Electronic well file reflects last reported production status as PR 8/1/2022. | | | | | | | | | |
| Corrective Action: Submit required Form 7(s) to COGCC per rule 413. Date: 08/17/2023 | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403465632 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182855 |
| 698600767 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182853 |
| 698600768 | Video Well Cap | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6182854 |