

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



1. Well sign.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



3. Pump Jack with motor removed.




4. View of gas meter run inside meter shed.

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



5. View of recording chart inside meter box dated 12-2-22.



6. View of meter test report attached to gas meter run dated 9-11-20.

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



7. View of weed/vegetation growth inside fencing.



8. View looking SW from inside fencing at erosion channel that starts on the S end of panel fencing.

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



9. View of erosion channel from outside fencing looking W.



10. View of erosion channel looking W/SW at edge of location and top edge of slope.

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



11. View of erosion channel looking SW downgrade of slope.



12. View of sediment deposit from erosion channel at base of slope.

Inspection Photos
Location Name: Bledsoe 1-25-3-44
API Number: 125-09083



13. View at base of slope looking NE towards well location.



14. One of four marked deadmen.