

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2023

Submitted Date:

07/26/2023

Document Number:

696305122**FIELD INSPECTION FORM**Loc ID 430128 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

26 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430129	WELL	PR	08/01/2020	OW	123-36056	Antelope J-F-20HZ	PR
430161	WELL	PR	10/01/2022	OW	123-36063	Antelope O-K-20HZ	PR
436063	WELL	PR	03/01/2021	OW	123-38909	Antelope O34-K31-20HNC	PR
436064	WELL	PR	04/01/2021	OW	123-38910	Antelope 24-21-20HC	PR
445624	WELL	PR	03/13/2020	OW	123-43138	State Antelope F11-29-32XRLNC	PR
445625	WELL	PR	03/25/2020	OW	123-43139	State Antelope A11-29-32XRLNC	PR
445627	WELL	PR	11/01/2022	OW	123-43140	Antelope 21-24-29HNC	PR
445628	WELL	PR	03/10/2020	OW	123-43141	State Antelope F21-29-32XRLNB	PR
445629	WELL	PR	03/13/2020	OW	123-43142	Antelope 11-14-29HNB	PR
449424	WELL	PR	03/16/2020	OW	123-44304	ANTELOPE O24-20-17XRLNC	PR
449425	WELL	PR	04/02/2020	OW	123-44305	Antelope J-20-17XRLNC	PR
449426	WELL	PR	03/28/2020	OW	123-44306	ANTELOPE 24-20-17XRLNB	PR
459639	WELL	PR	04/26/2020	OW	123-48964	Antelope E-20-17XRLNB	PR
459640	WELL	PR	04/26/2020	OW	123-48965	Antelope E14-20-17XRLNC	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank missing Capacity Label; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/18/2023
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	What appears to be Frac Sand or some type of Soild on South side of Location; see photos		
Corrective Action:	Pollution: Violation to water quality standards and classifications. Comply with reporting requirements in 906 and notify EPS within 24-hrs. Comply with 912 Series Rules	Date:	07/28/2023
Type	STORAGE OF SUPL		
Comment:	Unused Rip Rap on South Side of Location. See photos		
Corrective Action:	Comply with Rule 606	Date:	08/18/2023
Type	OTHER		
Comment:	SE Corner - Soild Waste - What appears to be Soilds Waste from Hydrovac Truck; see photos		
Corrective Action:	Pollution: Violation to water quality standards and classifications. Comply with reporting requirements in 906 and notify EPS within 24-hrs. Comply with 912 Series Rules	Date:	07/28/2023
Type	DEBRIS		
Comment:	Tumbleweed Debris at Wellheads; see photos		
Corrective Action:	Comply with Rule 606	Date:	07/31/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 14		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	#		
Comment:	30 Gas Meters		
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	400 BBLs	STEEL AST		40.379140,-104.352160	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	430129	Type:	WELL	API Number:	123-36056	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	430161	Type:	WELL	API Number:	123-36063	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436063	Type:	WELL	API Number:	123-38909	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436064	Type:	WELL	API Number:	123-38910	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	445624	Type:	WELL	API Number:	123-43138	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	445625	Type:	WELL	API Number:	123-43139	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	445627	Type:	WELL	API Number:	123-43140	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	445628	Type:	WELL	API Number:	123-43141	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	445629	Type:	WELL	API Number:	123-43142	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449424	Type:	WELL	API Number:	123-44304	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449425	Type:	WELL	API Number:	123-44305	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	449426	Type:	WELL	API Number:	123-44306	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	459639	Type:	WELL	API Number:	123-48964	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	459640	Type:	WELL	API Number:	123-48965	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Tumbleweed Debris at Wellheads. Tank missing Capacity Label. Unused Rip Rap on South Side of Location. What appears to be Frac Sand or some type of Soild on South side of Location. SE Corner - Soild Waste - What appears to be Soilds Waste form Hydrovac Truck.	petrie	07/17/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305123	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6195887