

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location #: 335085



Photo # 3717 From entrance to location



Photo # 3718 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC O29NE Pad

Location #: 335085



Photo # 3721 Location



Photo # 3722 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location #: 335085



Photo # 3723 Location



Photo # 3724 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location #: 335085



Photo # 3725 Location



Photo # 3726 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC O29NE Pad

Location #: 335085



Photo # 3732 Debris



Photo # 3734 Stained soils & gravel