

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2023

Submitted Date:

07/20/2023

Document Number:

696305157**FIELD INSPECTION FORM**Loc ID 455365 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10670Name of Operator: BISON IV OPERATING LLCAddress: 518 17TH STREET SUITE 1800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mathews, Erin	970-302-6171	emathews@mallardexploration.com	All Inspections
GILLEN, KATIE		kgillen@bisonog.com	
Edwardson, Dylan		dylan.edwardson@state.co.us	
Milne, Rachel		rmilne@bisonog.com	
Wolff, Todd		twolff@bisonog.com	
GARZA, TARAH		tgarza@bisonog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455365	LOCATION	AC			-	Shoveler Pad	AC

General Comment:

Inspected FacilitiesFacility ID: 455365 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Well Drilling**

Rig: Rig Name: Precision 460 Pusher/Rig Manager: Tawn
Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: Pass Test Pressure PSI: 1400 Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: Pawnee Waste

Comment: Current Well: 8-6-29-30-3HN
TD at 6617 FT, starting Curve kick off point at the time of this Inspection.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. At the time of this Inspection, Staff observed that the South Side of Location is not properly stabilized which resulted in sediment transfer into the stormwater ditch. The ditch and berm BMPs will now require maintenance as they are not properly functioning at the time of this inspection. See photos

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance as it should be in compliance at all times.

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Stormwater Ditch on South Side of Pad require maintenance per Rule 1002.f; see photos	petrie	07/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403472004	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189905
696305158	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189895