

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3754 From entrance to location



Photo # 3755 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3757 Location



Photo # 3758 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3759 Location



Photo # 3760 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3761 Location



Photo # 3762 Flowline heating insulation open ended

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3774 Flowline heating insulation open ended



Photo # 3769 Unmarked deadman #1

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3770 Same unmarked deadman from a different angle




Photo # 3771 Unmarked deadman #2

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3772 Same unmarked deadman from a different angle



Photo # 3775 Unmarked deadman #3

Inspection Photos
Location Name: CAERUS PICEANCE LLC P32 Pad
Location #: 334836



Photo # 3776 Same unmarked deadman from a different angle